


---

## REDI-Sensor™ Tips & Tricks: SE10002A & SE10003A

 REDI-Sensors SE10002A and SE10003A use advanced patented technology and is compatible with many high-line and auto-learn systems.

It is important to update TPMS scan tools regularly to have access to latest vehicle relearn coverage

Relearn challenges may occur if:

- The wrong make, model, year, sub-model or trim level is selected in the tool
- The relearn is not performed in entirety
- The vehicle is prematurely driven
- A tool with incompatible software is used



For many vehicles, the IDs must be written to the vehicle via OBDII using a properly formatted TPMS scan tool.

If an error occurs during installation or the relearn process, the sensors may need to be unlocked. This function can be found on the compatible scan tools shown below:



TPMS service work is to be handled by trained service professionals only.

For application and relearn information visit: [www.redi-sensor.com](http://www.redi-sensor.com).  
Technical Support: (800) 265-1818