

REDI-Sensor™

Multi-Application TPMS Sensors

AUMOVIO TSB 2022-1129A

Technology REDI-Sensor™ TPMS Sensors Require TPMS Tool Update and New Sensor Configuration Process

- An up-to-date compatible TPMS tool is required to configure the proper communication protocol.
- Even brand-new tools may have outdated software; and some current TPMS Tools do not support our latest technology.

Four New REDI-Sensor™ Part Numbers Include



■ SE10008

■ SE10006

■ SE10007

■ SE10005

Step 1 | Confirm TPMS Tool Compatibility using list below

COMPATIBLE TPMS TOOLS INCLUDE

- | | | | |
|------------------------------|----------------------|---------------------|-----------------|
| • Continental Autodiagnos D | • BARTEC Tech400PRO | • MATCO MAXTPMS 3.0 | • OTC 3838 |
| • Continental Autodiagnos SE | • BARTEC Tech450PRO | • SNAP-ON TPMS4 | • LAUNCH TSAP-5 |
| • ATEQ VT37 | • BARTEC Tech500PRO | • SNAP-ON TPMS5 | • MATCO MD56 |
| • ATEQ VT41 | • BARTEC Tech550PRO | • SNAP-ON TPMS6 | • NAPA 92-1541 |
| • ATEQ VT46 | • BARTEC Tech600PRO | • TOPDON TP-47 | • NAPA 92-1551 |
| • ATEQ VT47 | • BARTEC TechRitePRO | • TOPDON TP-48 | • SIMING SM57 |
| • ATEQ VT56 | • COSTCO VT56 | • Alligator AVT57 | • WURTH WU47 |
| • ATEQ VT57 | • DILL D48 | • BOSCH TPA300 | • LAUNCH TSAP-2 |
| • ATEQ VT67 | • HUF DT56 | • HAMATON H57 | • LAUNCH TSAP-3 |
| • BARTEC Tech300PRO | • MATCO MAXTPMS 2.0 | • HYBRID HT | |

Step 2 | Verify TPMS Tool has latest manufacturer software update

www.redi-sensor.com/updates or call our Tech Support at 800-265-1818 for assistance.

Step 3 | Follow new TPMS sensor configuration process

For new sensor configuration process instructions see next page or visit www.redi-sensor.com/updates or call our Tech Support at 800-265-1818 for assistance.

Latest Technology REDI-Sensor™ TPMS Sensor configuration process

<p><u>ATEQ VT56, VT37, VT41, VT46, VT47 or equivalent</u></p> <p><i>For REDI-Sensor SE10005, SE10006</i></p> <p>ATEQ Relearn</p> <ol style="list-style-type: none">1. Select Service or Service TPMS2. Select Make/Model/Year or VIN scan3. Select Relearn4. Trigger sensors following Relearn procedure <p><i>For REDI-Sensor SE10007, SE10008</i></p> <p>ATEQ Configure Sensor</p> <ol style="list-style-type: none">1. Select Program2. Select Sensor3. Select REDI-Sensor4. Select Make/Model/Year<ol style="list-style-type: none">a. Select Trigger to unlock protocolb. Repeat 'a' for each new REDI-sensorc. Return to Main menu, proceed to Relearn <p>ATEQ Relearn</p> <ol style="list-style-type: none">1. Select Service2. Select Make/Model/Year or VIN scan3. Select Relearn4. Trigger sensors following Relearn procedure	<p><u>Bartec Tech300Pro/Pro C, Tech400Pro, Tech500Pro, Tech450Pro, Tech550Pro, Tech600Pro and TechRitePro</u></p> <p><i>For REDI-Sensor SE10005, SE10006</i></p> <p>Bartec Relearn</p> <ol style="list-style-type: none">1. Select New TPMS Service2. Select Make/Model/Year or VINdicat3. Relearn: OBD, Stationary, or Drive4. Trigger sensors following Relearn procedure <p><i>For REDI-Sensor SE10007, SE10008</i></p> <p>Bartec Relearn</p> <ol style="list-style-type: none">1. New TPMS Service2. Make/Model/Year or VINdicat3. Program Sensors Menu<ol style="list-style-type: none">a. REDI-Sensor to Unlock protocolb. Repeat for each sensor as neededc. Return to previous menu4. Relearn: OBD, Stationary, or Drive5. Trigger sensors following Relearn procedure
<p><u>Snap-On TPMS4</u></p> <p><i>For REDI-Sensor SE10005, SE10006</i></p> <p>Relearn</p> <ol style="list-style-type: none">1. Select Relearn2. Select Make/Model/Year3. Select Trigger sensors following Relearn procedure <p><i>For REDI-Sensor SE10007, SE10008</i></p> <p>Configure Sensor</p> <ol style="list-style-type: none">1. Select Special Functions2. Select REDI-Sensor Unlock3. Select Make/Model/Year<ol style="list-style-type: none">a. Trigger to Unlock protocolb. Repeat for each sensor as needed.c. Return to previous menu <p>Relearn</p> <ol style="list-style-type: none">1. Select Relearn2. Select Make/Model/Year3. Trigger sensors following Relearn procedure	<p><u>Snap-On TPMS5</u></p> <p><i>For REDI-Sensor SE10005, SE10006</i></p> <p>Relearn</p> <ol style="list-style-type: none">1. Select TPMS2. Select Make/Model/Year3. Select Relearn4. Trigger sensors following Relearn procedure <p><i>For REDI-Sensor SE10007, SE10008</i></p> <p>Relearn</p> <ol style="list-style-type: none">1. Select TPMS2. Select Make/Model/Year3. Select Replace4. Select REDI-Sensor<ol style="list-style-type: none">a. Trigger to Unlock Protocolb. Repeat for each sensor as neededc. Return to previous menu5. Select Relearn6. Trigger sensors following Relearn procedure